Errata

NFPA 70®

National Electrical Code®

2011 Edition

Reference: Various
Errata No.: 70-11-1

The National Electrical Code Correlating Committee notes the following errors in the 2011 edition of NFPA 70, *National Electrical Code*.

How to Use this Errata Sheet

This is a list of errata to the first printing of the 2011 *NEC*®. A first printing is indicated by the numeral 1 as the last digit in the line of number appearing at the bottom of the first page.

1. Page 70-36 **110.14(C)(1):** Revise 310.15(B)(6) to 310.15(B)(7)

2. Page 70-78 **Figure 230.1:** Revise ''Source'' to ''Serving Utility'' and 230.49 to 230.32

3. Page 70-86 **230.90 Exception No. 5:** Revise 310.15(B)(6) to 310.15(B)(7)

4. Page 70-102 **Table 250.3:** Revise 300.50(B) to 300.50(C)

5. Page 70-116 **250.68(C)(2)(b):** Revise to read : ''By bonding the structural metal frame to one or more of the grounding electrodes, as specified in 250.52(A)(5) or (A)(7) that comply with 250.53(A)(2).''

6. Page 70-129 **250.180:** Revise 250.190 to 250.191

7. Page 70-139 **300.5(C) Exception No. 2:** Revise 330.10(11) to 330.10(A)(11)

8. Page 70-148 **310.10(E) Exception No. 2 (d):** Revise Table 310.13(D) to Table 310.104(D)

9. Page 70-148 **310.10(F):** Remove deletion bullet and add second paragraph to read : ''Cables rated above 2000 volts shall be shielded.''

10. Page 70-154 **Table 310.15(B)(16):** Add double asterisk to 18 AWG and 16 AWG copper

11. Page 70-178 **314.16(C)(1):** Revise 314.16(C)(2) to 314.16(C)(3)

12. Page 70-240 **392.18(E):** Revise 392.10(D) to 392.18(D)

13. Page 70-282 **410.36(A):** Revise 314.27(A)(A)(2) to 314.27(A)(2)

14. Page 70-287 **410.130(D):** Revise Part XIII to Part XII

15. Page 70-288 **410.140(D):** Revise Part XIV to Part XIII

16. Page 70-327 **430.75(A) Exception No. 1 (a):** Revise Part XI to Part XII

17. Page 70-397 **504.70 Exception:** Revise 501.15(F)(3) to 501.17

18. Page 70-435 **Figure 516.3(C)(1):** Revise 3050 m to 3050 mm

19. Page 70-435 **Figure 516.3(C)(2):** Revise 3050 m to 3050 mm in two locations

20. Page 70-562 **645.10(B)(5):** Revise 645.5(D)(2) or (D)(3) to 645.5(E)(2) or (E)(3)

21. Page 70-572 **670.3(B):** Revise 670.4(B) to 670.4(C)

22. Page 70-583 **680.25(B)(1):** Revise 250.30(A)(8) to 250.30(A)(3)

23. Page 70-708 **840.47:** Revise section number from 830.47 to 840.47

Issue Date: April 8, 2011

(Note: Electronic products and pamphlet reprints may have this errata incorporated. For current information about the NFPA Codes and Standards, including this errata, please see www.nfpa.org/codelist)

Copyright © 2011 All Rights Reserved
NATIONAL FIRE PROTECTION ASSOCIATION

Errata

NFPA 70®

National Electrical Code®

2011 Edition

Reference: Various
Errata No.: 70-11-2

The National Electrical Code Correlating Committee notes the following errors in the 2011 edition of NFPA 70, *National Electrical Code*.

How to Use this Errata Sheet

This is a list of errata to the first printing of the 2011 *NEC*®. A first printing is indicated by the numeral 1 as the last digit in the line of numbers appearing at the bottom of the first page.

1. Page 70-176: **Table 312.6(B), Note 3:** Change reference from 310.14 to 310.106(B).
2. Page 70-190: **324.42(B):** Change the reference in the last line from 800.133(A)(1)(c), Exception No. 2. to 800.133(A)(1)(d), Exception No. 2.
3. Page 70-233: **382.10(A):** Revise last two references from 406.4(D)(3)(b) & 406.4(D)(3)(c).to 406.4(D)(2)(b) & 406.4(D)(2)(c).
4. Page 70-234: **382.42(B):** Change cross reference from 800.133(A)(1)(c) Exception No. 2. to 800.133(A)(1)(d) Exception No. 2.
5. Page 70-282: **410.36(A):** Correct the second cross reference from 314.27(A)(A)(2) to 314.27(A)(2).
6. Page 70-342: **440.8:** Correct cross reference from 430.87 Exception to 430.87, Exception No. 1.
7. Page 70-348: **450.3(B), Exception:** Change cross reference to 430.72(C)(1) through (C)(5).
8. Page 70-815: Change running head to "Informative Annex E".

Issue Date: January 24, 2012

(Note: Electronic products and pamphlet reprints may have this errata incorporated. For current information about the NFPA Codes and Standards, including this errata, please see www.nfpa.org/codelist)

Copyright © 2012 All Rights Reserved
NATIONAL FIRE PROTECTION ASSOCIATION